

# Avonmouth Bridge Resurfacing

---



**Dave Sledge.**

**21<sup>st</sup> March 2013**

## Who Is This Chap?

---

### **Dave Sledge;**

30 years in the Highways Industry both Public and Private sector.

11 years in the Highways Agency


Incorporated Engineer.

Managed both PFI and maintenance contracts


Currently managing the Area 2 maintenance & renewals Contract in the South West.

Knows enough about “blacktop” to be jolly dangerous!

# Avonmouth Bridge?



# A Bit Closer.




# We All Like Pictures?

---



# Avonmouth Cross Section



## Some Facts.

---

1.4km complex multispan viaduct opened in 1975

Main span - Twin box girder, steel deck

Approaches- comp box girder, conc deck

60,000 vehicles per day (each direction)  
incl 7,200 HGVs

Major renewal carried out 1995 to 1999,  
including strengthening, widening and  
resurfacing

Avonmouth Bridge steel centre span is  
classed as “long span” – deflection at  
centre up to 400mm.



# Surfacing History

---

By 2001 failures occurring

Various Studies – TRL & various consultants

Jul 2005 – EMAC appointed – wholesale resurfacing required

Sep 2006 – Feasibility Study

Nov 2006 – Resurfacing workshop

March 2007 – Whole Life Costing exercise

May 2007 – Best Value Study

# Surfacing History

---

Last surface was hand laid

It had an Expected Life of 8 to 10 years –  
issues within 24 months

Porous nature of surface contributed to  
creation of pot holes

Bond between surface and waterproofing  
failing

Possibility of damage by welded deck  
repairs

Surface damage affecting waterproofing  
and could lead to damage to bridge  
structure beneath



# Design

---

Wide range of road surface temperatures due to exposed location and box girder construction.

Heavy traffic, 8 lane carriageway.

The design considered the surfacing and waterproofing to work compositely with the bridge deck.

Whole life costing used in selection process.

# Best Value.

---

**“determine the best long term solution to the resurfacing of Avonmouth Bridge”**

**Noise**

**similar structures**

*Skid resistance*

*Ride quality*

**Tensile bond**


**LOW permeability**

# Weighted Issues.

<i>Issues</i>	<i>Weighting</i>
Track Record Proven System	☑☑☑☑☑☑☑☑
Durability, Design, Life expectancy	☑☑☑☑☑☑☑☑
Serviceability rutting, frets, cracks etc	☑☑☑☑☑☑☑☑
Skid Resistance: in line with standards	☑☑☑☑☑☑☑☑
Adhesion: of WP and surfacing interfaces	☑☑☑☑☑☑☑☑
Tensile Bond: highest value used	☑☑☑☑☑☑☑☑
Low Permeability: reduced hydrostatic pressure	☑☑☑☑☑☑☑☑
Replaceability	☑☑☑☑☑
Maintainability – Efficacy of maintenance solution	☑☑☑☑☑☑☑☑
Ease of approval. Meets specs	☑☑☑
Drainage Surface and sub surface	☑☑☑☑☑☑
Thickness and layer control	☑☑☑☑☑☑☑☑
Joint reliability Mastic v Epoxy	☑☑☑☑☑☑☑☑
Fatigue/contribution to composite deck strength	☑☑☑☑☑☑☑☑
Flexibility of surfacing – compatible with steel deck	☑☑☑☑☑☑☑☑
Ability to omit central reserve and/or hard shoulder	☑☑☑☑☑
Noise to driver	☑☑
Noise to residents	☑☑☑☑☑☑☑☑
Spray	☑☑☑☑☑☑☑☑
Ride Quality	☑☑☑☑☑
Replacement cycle/TM/congestion	☑☑☑☑☑☑☑☑
Competitive supply	☑☑☑☑☑☑
Programme reliability	☑☑☑☑☑☑☑☑
Traffic Management Impact	☑☑☑☑☑☑☑☑
Weather susceptibility	☑☑☑☑☑☑☑☑
Local congestion caused	☑☑☑☑☑☑☑☑
CDM	☑☑☑☑☑☑☑☑
QA/QC Requirements	☑☑☑☑☑☑☑☑
Programme duration	☑☑☑☑☑☑☑☑
Build ability: tolerance to site conditions includes level control	☑☑☑☑☑☑☑☑

# Bridge Layers

---



# Waterproofing

---

## Approved options;

Bituminous sheet system – Usually used with a additional protective layer (APL)

Slurry Epoxy system – usually a thin squeegee layer but prone to deformation

Spray applied epoxy – A more tested system that can achieve high tensile strength with the APL.

## Additional Protection Layer?

---

TRL study in 1986 concluded that APLs provided protection during construction operations and as an indicator of the waterproofing below. This material was often a coloured sand carpet

However modern materials are less fragile and waterproofing often needs removal with the surfacing. Benefits are questionable.

Omitting the layer was considered to be a benefit to bond, tensile strength and weight.

# Performance & Surface Layer.

---

## Performance Layer (45 – 70mm)

Rolled asphalt

Stone mastic asphalt

Modified mastic asphalt (Gussasphalt)

## Surface Layer (20 – 50mm).

Thin surface SMA min 20mm lasts up to 10 years, is easy to lay and relatively impermeable.

Hot rolled asphalt (HRA) min' 45mm lasts up to 15 years, more complex to lay.

Mastic Asphalt. Min 20mm lasts up to 50 years, traditionally nasty to lay, requires a thin skid resistance surface.

**Modified Mastic Asphalt (Gussasphalt). Used in Europe, up to 50 years life and easier to lay and compact.**

# Whole Life Costs

---

HRA/ SMA Replacement every 12 years, 12 weeks construction

Modified Mastic Asphalt every 20 years, 12 weeks construction

Epoxy Asphalt 20 years life, 17 weeks construction

80 year time period.

Traffic Management was estimated to be almost £2 million.

Delay costs were modelled (QUADRO).

2007 - £4 million.

2018 - £15 million.

2066 - £41 million.

# Whole Life Costs.

---

## Concrete deck

Option	Total cost at Q3/2006 prices
Option C1 (Single layer modified HRA)	£219,525,000
Option C2 (Single layer Gussasphalt)	£127,210,000

## Steel Deck

Option	Total cost at Q3/2006 prices
Option S1A (Gussasphalt with high PSV chippings)	£52,383,000
Option S1B (Gussasphalt with high friction surface dressing)	£71,003,000
Option S2 (Epoxy asphalt)	£78,157,000

# The family tree of delivery.

---

**Client** Highways Agency.

**Tier 1** Balfour Beatty/ Mott Macdonald Joint Venture (EMAC).

**Tier 2** Stirling Lloyd

**Tier 3** Aechlimann International

**Tier 4** Hanson, Nynas.

# What is this “blacktop”?

---

## Gussasphalt;

Developed by Aeschlimann International of Switzerland.

Uses Nynas Endura N5 Binder

Trinidad Lake Asphalt.


High proportion of limestone filler.

Laid at 220 degrees C!

Low permeability avoiding “pumping” (less than 1% voids).

Few joints.

# The Layers.



# Resurfacing In Action!



# The laying Rails.



# What a Lovely Surface!



# Friction Course

---



## How Is It Today?



---

So far.....so good!

1 small incident related defect on the northbound carriageway which we are rectifying using blocks of material supplied at time of construction.

# Questions?

---



“Excuse me, but is this The  
Society for Asking Stupid  
Questions?”