

Road Surface Treatments Association

Steel mesh case histories

Richard Bennett


Maccaferri

Steelmesh

- Over 100 installations in UK since 2005
- Over 300 installations worldwide
- Extreme sites
 - Soft ground
 - Extreme temperatures
 - Widening
 - High wheel load
 - Junctions
 - Bus/ Crawler lanes




Steelmesh





Steelmesh







Steel mesh interlock







Installation - Unrolling and stretching







Installation - Rolling with PTR





Installation - Nailing





Installation - Slurry seal



Installation - Blinding





Installation - Paving



Installation - Problems







A4144, Abingdon Road, Oxford

- Heavily traficked section on alluvium, low CBR
 - Fixed kerb height
 - Shallow services
 - Norman causeway
- Required constant maintenance for fatigue cracking
- Resurfaced in 2003
 - Geogrids in the sub-base
 - Steel mesh nailed overlain by 260mm HDM
- No fatigue cracking after 8 years



A507, Ampthill Bypass, Bedfordshire

- Heavily trafficked bypass
- Resurfaced in 2001
 - 80mm overlay
- No return of cracking after 10 years





A157, Orby Bypass, Lincolnshire

- Soft ground
- Constructed in 2005
 - 100mm overlay





www.rsta-uk.org

State route, 453 Blair County, Pennsylvania, USA

- Reflection cracks from rocking concrete slabs
 - Grouted, steel mesh and 60mm overlay in 2002

No return of cracking in 9 years



B7052, Whauphill, Dumfries and Galloway

- Quarry road
- 1.6km section on peat
 - Required Monthly maintenance
 - Cracking and potholes
- Resurfaced in 2003
 - No maintenance in 11 years





Steel mesh installations

- A167 Durham, 1997
 - HA trial on old section of A1
- A631 Shepcote Lane, 2005
 - New heavy traffic to steelworks
- Moss roads Lancashire, 1991
 - 50km of roads on peat
- A9 Daviot, 2001
 - 4km Soft ground



B873, Sutherland

- Floating roads trial
 - Peat
 - Differential settlement
 - Expensive to excavate or pile
 - Wetting and drying cycle
 - Avoid disturbing the equilibrium
 - Geogrid in the sub-base reduces weight
 - Steel mesh in the asphalt controls cracking

B873, Floating road trials

Constructed in 1995

http://www.roadex.org





A75, Dumfries and Galloway

- Truck route links Stranger with M74
- Poorly drained section east of Newton Stewart
- Required constant maintenance during 80' and 90's
- Resurfaced in 1999
 - Regulating layer,
 - Steel mesh
 - 80mm overlay
- No cracking after 11 years







Road Surface Treatments Association

Thank you

Richard Bennett
Maccaferri